




Solder Sponge Soldering Station Usage Table



| EasyBraid Part # | EasyBraid Description | Use with Soldering Station/Workstand Model #: | | | |
|------------------|------------------------------|---|--|--|---|
| | | Hakko | Weller | Metcal | Hexacon |
| S1525-O-T | CENTER-HOLE, 1.5 IN X 2.5 IN | | SP60 | STSS-YS1 | |
| S2026-S-T | SLITS, 2.0 IN X 2.6 IN | | WECP, WTCP, EC-2002 | | |
| S2235-O-T | CENTER-HOLE, 2.2 IN X 3.5 IN | | | | 1001, 1002 |
| S2626-M-T | MULTI-HOLE, 2.6 IN X 2.6 IN | 927, 928, 936 | PH50, PH1201ESD, PH1201FE, PH1301ESD, PH1503 | | |
| S2626-O-T | CENTER-HOLE, 2.6 IN X 2.6 IN | 927, 928, 936 | PH50, PH1201ESD, PH1201FE, PH1301ESD, PH1503 | | |
| S2626-P-T | PLAIN, 2.6 IN X 2.6 IN | 927, 928, 936 | PH50, PH1201ESD, PH1201FE, PH1301ESD, PH1503 | | |
| S2626-S-T | SLITS, 2.6 IN X 2.6 IN | 927, 928, 936 | PH50, PH1201ESD, PH1201FE, PH1301ESD, PH1503 | | |
| S2745-S-T | SLITS, 2.7 IN X 4.5 IN | | EC-1000, EC-2000 | | |
| S3030R-O-T | ROUND, CENTER-HOLE, 3 IN | | | PS800, PS-900, MFR-1160, WS2 | |
| S3219-O-T | CENTER-HOLE, 3.2 IN X 1.9 IN | | | SP-200, MFR-1150, MFR-1110, MFR-1120, MFR-1140, MFR-1150, MFR-1161, ALL MX-500 & MX-5000S series, WS1, MFR-WSPT, MFR-WSDSU, WST, MX-WHPDC, MFR-WSDS, MFR-WSDSX | |
| S3444-O-T | CENTER-HOLE, 3.4 IN X 4.4 IN | | | | HD-890, HD-890-30, HD-891, HD-891-30, HD-891-MX, HD-892, HD-892-30, HD-892A |
| S3444-S-T | SLITS, 3.4 IN X 4.4 IN | | | | HD-891, HD-891-30, HD-891-MX |
| S4017-O-T | CENTER-HOLE, 4.0 IN X 1.7 IN | 926 | | | |